

Impact-area of Ejecta-Rays from the Port Hedland Crater or from the VLC, located near Kalgoorlie (Western Australia)

- Raman Spectra of selected Rock Samples - by Harry K. Hahn, 30.12.2021 -

Summary :

The Gravity Anomaly Map indicates that **Ejecta-material from the Ø 400 x 350 km Port Hedland Crater or from the Victoria Lake Crater (VLC) in East-Africa probably impacted here and formed these linear structures.** The Port Hedland Crater and the Victoria Lake Crater (VLC), which are both unknown craters yet, in all probability are large secondary craters that were caused by the Permian-Triassic Impact Event. For a detailed description of the Permian-Triassic Impact (PTI) Hypothesis please read **Part 1 (P1)** of my hypothesis. And for more information to the Ø 400 x 350 km Port Hedland Crater (PHC) please read pages 14-16, 20-21 and 24-28 of **Part 3 (P3)** and page 33 of **Part 2 (P2)** of my hypothesis.

The geological map shows large-scale structures (→ejecta lobes) in the Kalgoorlie-area which have strong similarities to structures caused by ejecta-blankets (-lobes) originating from an Impact Crater. These structures consist of rock-types different to the rock-types of the surrounding plains of the Yilgarn Craton. Compare these structures to the ejecta-rays (-lobes) from the Graterri Crater on Mars ! These ejecta-ray-structures penetrate the Yilgarn-Craton approximately down to a depth of 10 km ! In the Kalgoorlie area the Super-Pit gold-mine is located. The Gold and other rare- & heavy elements found in the area surely were ingredients of the PT-Impactor, the origin of the ejecta that impacted here.

I have collected some rock-samples from these ejecta-ray- (lobe-) structures in the Kalgoorlie area and have analysed these samples, mostly quartz, with Micro-Raman-Spectroscopy, to find out if they were exposed to a shock pressure which may indicate an Impact Event. And indeed that precisely is the case !!

The Raman-spectra of quartz from the Sample Sites 2, 4, 5, 13, 21, 27 & 31 provide first evidence for an Impact Event as the probable cause of these Ejecat-ray- (lobe-) structures in the Kalgoorlie Area. So far the samples from the Klagoorlie-area provided the best evidence for an Ejecta-Impact area !!

The following shifts of the main Raman-peaks, of the analysed quartz grains, to lower frequencies (which all indicate an impact shock event) were measured : 462, 261, 204 & 125 cm⁻¹ (Site 2_stone 1); 463, 260 & 205 (Site 2_stone 2); 463,260,204 (Site 4); 463,260/266 (Site 5); 463,261,125 (Site 21); 463,261,205,125 (Site 27); 463,257/267,204,125 (Site 31); 260,126 (Site 5_st.2) & 204, 126 cm⁻¹ (Site 13) (→ see explanation in **Appendix 1** at page **28** : Overview : The Raman bands (peaks) of shocked Quartz)




Microscopic images of a number of analysed quartz grains **will provide further proof for a shock event PDFs** (planar deformation features) seem to be present in some samples ! (→ images on **pages 4 to 17**)

All spectra were made with a **BRUKER Senterra-II Raman Microscope** (wavenumber precision <0.1cm⁻¹)


- Images of the analysed rock samples and photos of the sample sites are in the Appendix at **page 18**.
- More images of all sample sites are available on www.permiantriassic.de or www.permiantriassic.at
- References : see **page 29** / and pages 14-16, 20-21 and 24-28 of **Part 3 (P3)** of my hypothesis.

Note : A shock pressure of 20 GPa exceeds every pressure caused by normal terrestrial metamorphism. The indicated shock pressures of ≈20-22 GPa therefore in general point to an impact shock event.

Gravity Anomaly Map of the Kalgoorlie Area



Gravity Anomaly Map of SW-Australia





Geological Map of South-West-Australia →with sample site area marked on the map



The thin ejecta-ray-structures visible on the gravity anomaly map of Western Australia as linear red (positive) anomalies, were caused either by the **Ø400x350km Port Hedland Crater**

(=Bengal Bay Crater) or by the Victoria Lake Impact Crater. According to my Permian-Trassic Impact (PTI) hypothesis the Port Hedland Crater and VLC are big secondary-craters caused by the **PT-Impact**. Bengal Bay in India probably was also caused by the Port Hedland (=Bengal Bay) Crater! The topographic map below shows the original situation at the time of the PT-Impact Event. The gravity anomaly map indicates a number of linear eject-ray-structures (red) on the Yilgarn Craton which are (nearly) parallel.



Ø 400x350 km Port Hedland Crater





Ejecta-Rays have formed the Kalgoorlie Area (→ an important Mining Area) :
A comparison of the ejecta-ray-structures of the **Graterri Crater** on planet Mars with the structures visible on the geological map of the Kalgoorlie Area shows clear similarities. The ray- & lobe- structures have similar shapes as the longish & „lumpy“ ejecta-structures caused by the **Graterri Impact Crater**, → an Impact Crater on a planet with atmosphere. The strongest indication for an ejecta-impact area comes from the Gravity Anomaly Map (→ see map). The red-colored positive anomalies are arranged in a parallel pattern on the Yilgarn Craton. Source of the ejecta-rays is the Port-Hedland Crater or the VLC-Crater according to my **PTI—hypothesis**. In Kalgoorlie the large **Super-Pit gold-mine** is located. The gold here is mainly present in **Telluride Minerals** within Pyrite. **Tellur** & Gold are rare elements which surely were ingredients of the PT-Impactor together with other rare- & heavy elements found in the area like Rare Earth Metals, Nickel, Co, Ag, Zn, Cu, Cr, V etc.

Graterri Crater on Mars:


Compare the shape of the Ejecta-Lobes and -Rays !!




The cross-sections show that the ejecta-rays of the Port Hedland Crater (the nearly linear multi- colored structures visible on the geological map) have penetrated the Yilgarn Craton down to a **depth of around 5 to 10 km** !




Sample Site 2 : Stone 1_spectra 1 indicates : Quartz



Detail : Image size : ~ 500 x 400 μm



Detail : Image size : ~ 250 x 200 μm



Sample :




462


—462
—398
—352
—261
—204
—125

The spectral lines **462, 261, 204 and 125** indicate that the Quartz was exposed to a shock pressure of ≥ 22 GPa !


Sample Site 2 : Stone 2_spectra 1 indicates : Quartz





Detail : Image size : ~ 300 x 200 μm



Detail : Image size : ~ 150 x 100 μm




Sample :



The spectral lines **463, 260** and **205** indicate that the Quartz was exposed to a shock pressure of $\geq 22 \text{ GPa}$


Sample Site 4 : Stone 1_spectra 1 indicates : Quartz



Sample :




463




The spectral lines **463, 260 and 204** indicate that the Quartz was exposed to a shock pressure of $\approx 22 \text{ GPa}$!


Detail : Image size : $\sim 500 \times 400 \mu\text{m}$




Detail : Image size : $\sim 250 \times 200 \mu\text{m}$




Sample Site 5 : Stone 1_spectra 1 indicates : Quartz



Detail : Image size : ~ 500 x 400 μm



Detail : Image size : ~ 250 x 200 μm



Sample :



463

—463


—396
—353

—260
—206

—128

The spectral lines **463**, and **260/266** indicate that the Quartz was exposed to a shock pressure of ≈ 22 GPa !

Sample Site 21 : Stone 1_spectra 1 indicates : Quartz




Sample :




463

463
—
397
—
389
—
389
—
350
—
261
—
206
—
125


The spectral lines **463, 261, 206 and 125** indicate that the Quartz was exposed to a shock pressure of ≈ 22 GPa !




Detail : Image size : $\sim 500 \times 400 \mu\text{m}$



Detail : Image size : $\sim 250 \times 200 \mu\text{m}$



Sample Site 27 : Stone 1_spectra 1 indicates : Quartz




Sample :




The spectral lines **463, 261, 205 and 125** indicate that the Quartz was exposed to a shock pressure of ≈ 22 GPa !



Detail : Image size : $\sim 500 \times 400 \mu\text{m}$




Detail : Image size : $\sim 250 \times 200 \mu\text{m}$




Sample Site 31 : Stone 1_spectra 1 indicates : Quartz



Detail : Image size : ~ 500 x 400 μm



Detail : Image size : ~ 250 x 200 μm



Sample :





463

— 508 — 463 — 399 — 366 — 257 — 204 — 125 — 104 — 93

The main spectral lines **463, 257/267, 204 and 125** indicate that the Quartz was exposed to a shock pressure of ≈ 22 GPa !

Sample Site 2 : Stone 3_spectra 1 indicates : Erdite, Allanite





CrystalSleuth: EXTRACT_KAL_2-brauner Stein.0_000002.0


File Edit Mode Help



Sample :




Sample Site 5 : Stone 2_spectra 1 indicates : Quartz




Sample :




The spectral lines **260** and, **126** indicate that the Quartz was exposed to a shock pressure of ≈ 22 GPa !




Detail : Image size : $\sim 500 \times 400 \mu\text{m}$




Detail : Image size : $\sim 250 \times 200 \mu\text{m}$




Sample Site 13 : Stone 1_spectra 1 indicates : Quartz



Detail : Image size : ~ 500 x 400 μm




Detail : Image size : ~ 250 x 200 μm



Sample :



Sample Site 18 : Stone 1_spectra 1 indicates : **Rutile** (Titanium-Dioxide)




→ Sample from the Super-Pit Gold Mine


Sample :




CrystalSleuth: EXTRACT_KAL_18 (SP)_kleiner grauer_0_000005.0
File Edit Mode Help




R050417
Rutile
TiO₂
Champion mine, Mono County, California, USA



Sample Site 21 : Stone 3_spectra 1 indicates : Graphite, Emplectite, Sugilite




Sample :



CrystalSleuth: EXTRACT_KAL_21_schwarzer stein.0_000002.0

File Edit Mode Help

Spectra List



File Manager | SpecEdit | Raman Library | X-Ray |


% Match:	Spectrum Name:	RRUFF ID:
64	Graphite (532nm)	R090047
36	< Emplectite (532nm)	R070307
35	< Trolite (532nm)	R070242
35	< Naliknite (532nm)	R070219
35	< Sillimanite (532nm)	R061054
35	< Pavonite (532nm)	R070570
34	< Mordenite (532nm)	R061118
33	< Trachite (532nm)	R060623
33	< Krupakite (532nm)	R070310
32	< Krutalte (532nm)	R060381
32	Dachardite-Na (532nm)	R061116
32	Finegrite (532nm)	R070463

R070684
Sugilite
KNa₂Li₃Fe₂Si₁₂O₃₀
Iwagi Island, Inland Sea (Setonaikai), Ehime Prefecture, Japan


R090047
Graphite
C
Merelani, Tanzania

R070307
Emplectite
Cubis_2
Schwarzenberg District, Erzgebirge, Saxony, Germany


Search




Sample Site 21 : Stone 2_spectra 1 indicates : Quartz




Sample :




Detail : Image size : ~ 500 x 400 µm



Detail : Image size : ~ 250 x 200 µm



Sample Site 28 : Stone 1_spectra 1 indicates : Dolomite, Sahamalite-(CE)




Sample :





CrystalSleuth: EXTRACT_KAI_28-großer-bräunlicher (rechteckig)-korngrenze_0_00002.0

File Edit Mode Help

Spectra List



Detail : Image size : ~ 250 x 200 µm



Appendix 1 : Photos of the rock samples from the analysed sample sites :


→ See next page !

Please note : Photos of all Sample Sites & Rock Samples are available on my website :


→ Samples of the Kalgoorlie Area or here : [Kalgoorlie Area](#)

Geological Map of SW-Australia

Location where samples were collected :




→ 4 Geological Maps joined together :






→ Geological Maps can be downloaded here :

<http://www.geoscience.gov.au/>

Then go to "Geology" – 1:250K Geological Maps and search for the required map



The sections of the ejectarays of the Port Hedland Crater (the nearly linear multi-colored structures) have penetrated the Yilgarn Craton down to a depth of around 5 to 6 km !



2



2 | 30° 54,591 S | 121° 12,552 E | 8 m | West-Australia (SW)_Kalgoorlie area

Sample site 2



4




5




Sample site 5




Sample site 18 – The Super-Pit Gold Mine (Kalgoorlie)



Spectrum indicates : shocked Quartz → note the deformed quartz stones !



Sample site 21



Spectrum indicates : Grapite, Sugilite


--> Iron-bearing mineral




Sample site 21

Pillow-lava field





Sample site 27



28



Sample site 28





Sample site 31



Appendix 2 : A short overview : The Raman bands (peaks) of Quartz shocked with 22-26 GPa


In order to verify a sample site as an impact site or impact structure, [shock-metamorphic effects](#) must be discovered in the rocks of the sample site. This can be done by different methods.

For example with the help of PDFs (planar deformation features) which are visible in the quartz with the help of a microscope. However this requires careful preparation of the samples and expertise.

Another, easier method, is the use of a RAMAN microscope. Micro-RAMAN Spectroscopy on quartz grains in the samples can provide the first evidence for a shock event, that was caused by an impact.


Mc Millan et al. (1992) and others have shown that the main RAMAN-peaks of Quartz shift towards lower frequencies if the Quartz was exposed to a shock-pressure > 15 GPa. → see diagram below

The shift of the main quartz RAMAN-peaks can be used to identify quartz that was shocked by an impact



Quartz shocked with **22 GPa** and **26 GPa** shows shifts of the main RAMAN-peaks of $1 - 4 \text{ cm}^{-1}$ to lower frequencies

Appendix 3 : Raman spectra of (W) weakly-shocked & (M) moderately-shocked Alkali-Feldspar



Weakly shocked alkali feldspar mainly developed irregular fractures and undulatory extinction. Note that the Raman-lines 210 and 765 are missing in the w-shocked feldspar, and an additional line at ≈ 150 appears.

The shock pressure for the w-shocked feldspar was estimated to be between 5 and 14 GPa

References :

Photos of Sample Sites & Rock Samples are available on : Samples of the Kalgoorlie Area or here : [Kalgoorlie Area](#)

Find more information to the linear Ejecta-Ray structures in W-Australia in Parts 2 & 3 of my hypothesis - by Harry K. Hahn
Please read pages 14-16, 20-21 & 24-28 of [Part 3 \(P3\)](#) & page 33 of [Part 2 \(P2\)](#) of my hypothesis (→ weblinks below !)

Also read my Raman-analyses to rock samples from the **Geraldton area ; Southern-Cross-area & Margaret-River area !!**
→ You can find these analyses either on [www.vixra.org](#) or on [www.archive.org](#) → under my author name : Harry K. Hahn

The Permian-Triassic (PT) Impact hypothesis - by Harry K. Hahn - 8. July 2017 :

Part 1 : [The 1270 X 950 km Permian-Triassic Impact Crater caused Earth's Plate Tectonics of the Last 250 Ma](#)

Part 2 : [The Permian-Triassic Impact Event caused Secondary-Craters and Impact Structures in Europe, Africa & Australia](#)

Part 3 : [The PT-Impact Event caused Secondary-Craters and Impact Structures in India, South-America & Australia](#)

Part 4 : [The PT-Impact Event and its Importance for the World Economy and for the Exploration- and Mining-Industry](#)

Part 5 : [Global Impact Events are the cause for Plate Tectonics and the formation of Continents and Oceans \(Part 5\)](#)

Part 6 : [Mineralogical- and Geological Evidence for the Permian-Triassic Impact Event](#)

Alternative weblinks for my Study **Parts 1 - 6 with slightly higher resolution** : [Part 1](#), [Part 2](#), [Part 3](#), [Part 4](#), [Part 5](#), [Part 6](#)

Parts 1 – 6 of my PTI-hypothesis are also available on my website : [www.permiantriassic.de](#) or [www.permiantriassic.at](#)

Shock-metamorphic effects in rocks and minerals - <https://www.lpi.usra.edu/publications/books/CB-954/chapter4.pdf>

Shock metamorphism of planetary silicate rocks and sediments: Proposal for an updated classification system

Stöffler - 2018 - Meteoritics & Planetary Science – Wiley: <https://onlinelibrary.wiley.com/doi/epdf/10.1111/maps.12912>

A Raman spectroscopic study of shocked single crystalline quartz - by P. McMillan, G. Wolf, Phillip Lambert, 1992

<https://asu.pure.elsevier.com/en/publications/a-raman-spectroscopic-study-of-shocked-single-crystalline-quartz>

alternative : <https://www.semanticscholar.org/paper/A-Raman-spectroscopic-study-of-shocked-single-McMillan-Wolf/cfaaf6eb3e46fb2912fb91c7acf40e88e721132>

Raman spectroscopy of natural silica in Chicxulub impactite, Mexico - by M. Ostroumov, E. Faulques, E. Lounejeva

https://www.academia.edu/8003100/Raman_spectroscopy_of_natural_silica_in_Chicxulub_impactite_Mexico

alternative : <https://www.sciencedirect.com/science/article/pii/S1631071302017005>

Shock-induced irreversible transition from α-quartz to CaCl₂-like silica - Journal of Applied Physics: Vol 96, No 8

<https://aip.scitation.org/doi/10.1063/1.1783609>

Shock experiments on quartz targets pre-cooled to 77 K - J. Fritz, K. Wünnemann, W. U. Reimold, C. Meyer

https://www.researchgate.net/publication/234026075_Shock_experiments_on_quartz_targets_pre-cooled_to_77_K

A Raman spectroscopic study of a fulgurite – by E. A. Carter, M.D. Hargreaves, ...

https://www.researchgate.net/publication/44655699_Raman_Spectroscopic_Study_of_a_Fulgurite

alternative : <https://royalsocietypublishing.org/doi/abs/10.1098/rsta.2010.0022>

Shock-Related Deformation of Feldspars from the Tenoumer Impact Crater, Mauritania - by Steven J. Jaret

<https://trace.tennessee.edu/cgi/viewcontent.cgi?article=1002&context=pursuit>

A Study of Shock-Metamorphic Features of Feldspars from the Xiuyan Impact Crater - by Feng Yin, Dequi Dai

https://www.researchgate.net/publication/339672303_A_Study_of_Shock-Metamorphic_Features_of_Feldspars_from_the_Xiuyan_Impact_Crater

Shock effects in plagioclase feldspar from the Mistastin Lake impact structure, Canada – A. E. Pickersgill – 2015

<https://onlinelibrary.wiley.com/doi/pdf/10.1111/maps.12495>

Shock Effects in feldspar: an overview - by A. E. Pickersgill

<https://www.hou.usra.edu/meetings/lmi2019/pdf/5086.pdf>

ExoMars Raman Laser Spectrometer RLS, a tool for the potential recognition of wet target craters on Mars

https://www.researchgate.net/publication/348675414_ExoMars_Raman_Laser_Spectrometer_RLS_a_tool_for_the_potential_recognition_of_wet_target_craters_on_Mars